



Limited Visual Dam Safety Inspection Summary Report

MA-097

Kolea Reservoir

Maui, Hawaii

Prepared by:

**U.S. ARMY CORPS OF ENGINEERS
HONOLULU ENGINEER DISTRICT**

**STATE OF HAWAII
DEPARTMENT OF LAND AND NATURAL RESOURCES**

May 2006

Limited Visual Dam Safety Inspection Conducted on: 05 April 2006

I. Purpose

Due to disaster occurrences of periodic heavy rains and flooding, which has caused extensive damage to property and loss of lives, the Governor has issued a State of Emergency Proclamation extending from February 20, 2006 to April 9, 2006. In light of the tragic failure of the Kaloko dam on Kauai and the continued forecast of heavy rains, emergency inspections of all regulated dams in all counties are being undertaken.

These inspections are for the purpose of determining if any of the regulated dams and reservoirs in the City and County of Honolulu, Maui County or Hawaii County, are suspect for immediate concern to the downstream area under the prolonged conditions of heavy rain showers.

II. Authority

Inspections are authorized under the Hawaii Dam Safety Act of 1987, Chapter 179D "Dams and Reservoirs" of Hawaii Revised Statutes, and Title 13, Subtitle 7, Chapter 190, "Dams and Reservoirs" of the Hawaii Administrative Rules.

These inspections are being conducted under joint agreements of the U.S. Army Corps of Engineers (USACE), the U.S. Department of Agriculture Natural Resources Conservation Service (NRCS), and the State of Hawaii. The Memorandum of Agreement with the U.S. Army Corps of Engineers is entered into pursuant to 10 U.S.C. § 3036(d)(2), and the Intergovernmental Cooperation Act (31 U.S.C. §6505), and established via support agreement number DL-06-01.

III. Scope

Visual inspection will be made on parts of the embankment and appurtenant works readily available and visible for inspection by the inspection team at the time of the inspection. Such parts and appurtenant works would include the upstream slope, crest, downstream slope, abutments and toes, outlet works, and spillway.

On the date of this limited visual inspection, there may appear to be no immediate threat to the safety of the dam, however no assurance can be made regarding the dam's condition after this date. Subsequent adverse weather and other factors may affect the dam's condition.

IV. Limitations of Findings and Recommendations

The inspection is based only on visible features/areas of the dam on the day of inspection. The inspection does not entail detailed stability, hydrologic, hydraulic, or seismic investigations. This inspection is not a formal phase I or phase II dam safety inspection and does not include a review or evaluation from each specialist of an inspection team, such as a geologists, civil, geotechnical, structural, or hydraulics engineer. The owner should verify the findings of this report and take corrective actions. The owner may submit to the State alternative corrective actions that are certified by a licensed professional engineer in the State of Hawaii experienced in the design and construction of dams. This inspection does not relieve the owner/operator from their responsibility to conduct routine inspections, maintenance, repairs, modifications, monitoring, documentation, and/or investigative studies.

V. Inspection Team

<u>Organization</u>	<u>Name /Title</u>
U.S. Army Corps of Engineers	Henri Mulder, P.E. Civil Engineer
State of Hawaii, Dept. of Land and Natural Resources	Hiram Young Engineer
State of Hawaii, Dept. of Land and Natural Resources	Ke'alii Kimokea Division of Forestry & Wildlife

VI. Owner's Representatives Present

East Maui Irrigation Company	Mark Vaught
East Maui Irrigation Company	Henry Robbello

VII. Summary Report Team

<u>Organization</u>	<u>Name</u>
U.S. Army Corps of Engineers	Derek Chow Bill Empson
State of Hawaii, Dept. of Land and Natural Resources	Denise Manuel Edwin Matsuda

VIII. Dam Type

The dam appeared to be an earthen embankment dam.

IX. Dam Classification

The current hazard classification of this dam is: Undetermined

The classification should be determined.

Hazard Potential Classification based on the following:

Category	Loss of Life	Economic Loss
Low	None Expected	Minimal (undeveloped to occasional structures or agriculture)
Significant	Few (No Urban development and no more than a small number of inhabitable structures)	Appreciable (Notable agriculture, industry or structures)
High	More than a few	Extensive community, industry or agriculture.

Based on inventoried storage and height data, the size classification of the dam is: Most likely Intermediate but insufficient information is available to inspectors to make a determination.

Size Classification based on the following:

Category	Storage (Acre-Feet)	Height (feet)
Small	< 1000	< 40
Intermediate	> 1000 and < 50,000	> 40 and < 100
Large	> 50,000	> 100

X. Summary of Inspection

Condition Rating Criteria: The conditional terms in this report are used to generally describe the conditions below. Inspections, monitoring, and additional investigations are considered to be incidental to all condition ratings.

Satisfactory	Expected to fulfill intended function.
Fair	Expected to fulfill intended function, but maintenance is recommended.
Poor	May not fulfill intended function; maintenance or repairs are necessary.
Unsatisfactory	Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
Unknown	Not visible, not accessible, not inspected, or unable to determine the condition rating based on the observation taken.

A. General appearance:

The dam consists of an earthfill embankment. The dam is approximately 48 feet tall and 300 feet long. The dam is feed by natural stream. The purpose of the reservoir is irrigation.

Findings and Corrective Actions:

- a. The Owner shall maintain documentations including Construction plans, specifications, improvements, modifications, Operations and Maintenance Manuals and routine inspection logs for this dam facility.
- b. An EAP is required for all dams regardless of hazard class. Submit EAP if developed for the facility.
- c. Access to site appears to be satisfactory.
- d. Submit current Operations and Maintenance Manual or Procedures for this dam / reservoir facility.
- e. Emergency Alarms / Monitors: There were no alarms or monitors observed on this reservoir.
- f. Power / Communication: There were no communication systems observed on this reservoir.

B. Access / Security:

Access to the dam was accomplished via a private roadway from a State Highway. A four-wheel drive vehicle is required.

Security issues. Access to the dam is controlled by a locked gate.

C. Intake Works:

The reservoir is on a natural stream.

Findings and Corrective Actions:

- a. The intake works were not inspected.

D. Reservoir:

The reservoir level was full and there was a slight flow over spillway at the time of inspection.

The reservoir pool varies depending on rainfall.

There was no staff gage, so the actual level is not known.

Findings and Corrective Actions:

- a. The reservoir was not inspected.

E. Upstream Slope: (Satisfactory)

The upstream slope was 1 on 1.

The upstream slope is protected by dumped rock.

Erosion on the upstream slope was not observed at the time of inspection.

The brush on the slope has been recently cut.

Findings and Corrective Actions:

- a. The upstream slope appeared to be in satisfactory condition, no corrective actions are required at this time.

F. Crest: (Satisfactory)

The dam crest was approximately 35 feet wide.

There is an unsurfaced road on the crest.

The crest has low ground cover with 3" to 6" tall grass.

Findings and Corrective Actions:

- a. The dam crest appeared to be in satisfactory condition, no corrective actions are required at this time.

G. Downstream Slope: (Fair)

The downstream slope angle could not be determined as it was not visible due to the dense bamboo.

Access to the downstream slope is a roadway to outlet works.

Erosion to the downstream slope was not determined, because the site could not be inspected due to dense vegetation (bamboo).

There was lots of bamboo on the slope. The owner routinely cuts the bamboo, however it grows very fast. The slope could not be inspected due to dense vegetation and bamboo.

There was no seepage observed at the time of inspection.

Findings and Corrective Actions:

- a. The downstream slope appeared to be in fair to poor condition and requires corrective action.
- b. The down stream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection. Recommend cutting the bamboo twice a year or spray to kill.

H. Abutments / Toe: (Fair)

The abutments/toe could not be inspected due to the dense vegetation.

There was a lot of bamboo on the abutments.

Seepage was observed in the outlet channel at a distance of about 10 feet from the outlet conduit. The seepage was flowing clear at a rate of approximately 20-gpm.

Owner should monitor the seepage for change in flowrate and condition (i.e., seepage removing soil from the foundation).

Findings and Corrective Actions:

- a. The abutments/toe appeared to be in fair to poor condition and requires corrective action.

- b. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- c. Monitor the seep below outlet pipe for change in flowrate or condition (i.e., seep moving soil).

I. Outlet Works: (Satisfactory)

The outlet consists of a 12" diameter steel pipe.

The control of the outlet is with a valve that is on the upstream side.

Findings and Corrective Actions:

- a. The outlet works were not tested.
- b. The outlet works appeared to be in satisfactory condition, no corrective actions are required at this time.

J. Spillway: (Satisfactory)

This spillway is consisted of a channel cut into rock on left abutment.

The dimension is 30 feet.

The spillway approach was clear.

Erosion was not observed at the time of inspection.

Findings and Corrective Actions:

- a. The Spillway appeared to be in satisfactory condition, no corrective actions are required at this time.

K. Down Stream Channel: (Unknown)

Findings and Corrective Actions:

- a. The downstream channel was not inspected.

XI. Additional Comments:

There is no immediate threat to the safety of the dam.

Recommendation:

- 1) Monitor the seep just below the outlet pipe in the exit channel. Monitor the seep for changes in flowrate or condition (i.e., seep moving foundation material). Owner should have a geotechnical engineer, knowledgeable in the evaluation, design, and construction of dams; conduct a detailed evaluation of the seepage conditions.
- 2) Owner needs to routinely remove underbrush and bamboo from the downstream slope. Bamboo should be cut and removed at least twice a year or sprayed with herbicide and removed.
- 3) The owner should continue with removing brush and trees from the embankment. Grasses should be kept short.

PHOTOGRAPHS


MA-097 Kolea Reservoir

MA-097 Kolea Reservoir



097 seep - View of the seep located about 10 feet downstream of the outlet pipe in the exit channel. Owner should routinely monitor the seep for change in flowrate or condition.

MA-097 Kolea Reservoir



097 Spillway. The spillway was slightly flowing during the inspection. The reservoir is full.

MA-097 Kolea Reservoir



097 upstream - Upstream slope of the dam. Note recently cut brush on the slope.

FIELD INSPECTION SHEETS

Dam ID: * MA-0097

KOLEA RESERVOIR

Vulnerability Index:

Extreme	High	Moderate	Low
1	2	3	4

Inspection No: _____

Date: 4/5/2006

STATE OF HAWAII - DLNR
DAM SAFETY INSPECTION SHEET

Inspection Type: Visual Dam Safety Inspection

Persons Present

Affiliation

Phone Number

HENRI MULDER

US Army Corps of Engineers

HIRAM YOUNG

DLNR - ENGINEER

MARK VAUGHT

EMI (EAST MAUI IRRIGATION)

HENRY PORRELLLO

EMI

KE'ALII

DLNR - FORESTRY

Weather Condition:

☐ Rain previous day☐ Rainy☐ Drizzle / Mist☒ Cloudy/Overcast☐ Partly Cloudy☐ Sunny☒ Dry

Comments: _____

1. General: (Information currently on file, update as required)

Dam/Res. Name KOLEA RESERVOIR

Owner East Maui Irrigation Company

(C006)

Owner Contact Mr. Mark Vaught

Owner Ph. _____

Lessee N/A

Lessee Ph. _____

O & M Contractor East Maui Irrigation Company

O & M Ph. _____

Nearest Town _____

Latitude 20.875 ° (decimal)

County MAUI

Longitude 156.1933 ° (decimal)

Tax Map Key(s) (2) 1-1-001: 050

Dam Status

A: _____

Hazard Potential

U: _____

Dam Size _____

Year Completed 1901

Dam Length 300 ft.

Dam Height 48 ft.

Normal Storage 31 ac.ft.

Max. Storage 34 ac.ft.

Max. Surface Area _____ ac.

Drainage Area _____ mi.

Spillway Type _____

Max. Spillway Q 31 cfs

Owner owns land under dam facility: _____

Emergency Action Plan on file with the Department: NO

Reports on file with the Department: None on file.

2. Questions for Owner's Rep.:

	Yes	No	Unknown	Comments
Construction Plans Available	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Site / Facility Map	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Operation & Maintenance Manual	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Emergency Action Plan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>Owner is currently preparing an EAP</i>
Modifications / Improvements	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Conduct Routine Inspections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Conduct Routine Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Vehicle access to site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Access during heavy rains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Access when spillway is flowing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input checked="" type="checkbox"/> Requires 4-Wheel Drive
Other Studies Conducted	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Phase I <input type="checkbox"/> Phase II <input type="checkbox"/> Hydraulics <input type="checkbox"/> Stability <input type="checkbox"/> Hazard <input type="checkbox"/> Seismic <input type="checkbox"/> Other: _____
Incident History	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Breached <input type="checkbox"/> Overtop <input type="checkbox"/> Slide <input type="checkbox"/> Down stream Flooding <input type="checkbox"/> Other: _____
Reservoir's Current Use	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sediment <input checked="" type="checkbox"/> Irrigation <input type="checkbox"/> Recreation <input type="checkbox"/> Flood Control <input type="checkbox"/> Drinking Water <input type="checkbox"/> Power Generation <input type="checkbox"/> Other: _____

Findings and Corrective Actions:

- ☒ a. The Owner shall maintain documentations including Construction plans, specifications, improvements, modifications, Operations and Maintenance Manuals and routine inspection logs for this dam facility.
- ☐ b. An Emergency Action Plan (EAP) is on file with the department, submit any updates as applicable.
- ☐ c. An EAP is required for High Hazard Dams. Submit an updated EAP for this facility.
- ☒ d. An EAP is recommended for all dams regardless of hazard class. Submit EAP if developed for the facility.
- ☐ e. Submit narrative and additional information detailing the improvements, modifications, and/or alterations at the dam site, unless covered by approved dam permit.
- ☐ f. Routine inspection logs were not inspected.
- ☐ g. Dam owners shall provide for routine inspection of the dam.
- ☐ h. The dam did not appear to be maintained on a regular basis.
- ☒ i. Access to site appears to be satisfactory.
- ☐ j. There is no vehicular access to the dam site. Operational and emergency plans need to reflect this deficiency or access provided.
- ☐ k. Access to dam is questionable during severe weather conditions and/or spillway overflows. Operational plans and emergency plans need to reflect this deficiency or access provided.
- ☐ l. Provide a detailed narrative of the incident, responses taken, and any damages incurred. Dam owners are required to promptly advise the department of any sudden or unprecedented flood or unusual or alarming circumstance or occurrences which may adversely affect the dam or reservoir.
- ☒ m. Submit current Operations and Maintenance Manual or Procedures for this dam / reservoir facility.
- ☐ n. Submit Site or Facility Map of this Dam which identifies the location of major features including outlet works controls and conduits.
- ☐ o. _____

Additional Requirements:

The following investigative study(s) are:

Required Recommended

- | | | |
|--------------------------|--------------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> | Phase I Study |
| <input type="checkbox"/> | <input type="checkbox"/> | Phase II Study (Including <input type="checkbox"/> Seepage <input type="checkbox"/> Hydrology/Hydraulics <input type="checkbox"/> EAP) |
| <input type="checkbox"/> | <input type="checkbox"/> | Hydrology and Hydraulics (including Probable Maximum Flood and spillway capacity) |
| <input type="checkbox"/> | <input type="checkbox"/> | Stability Analysis |
| <input type="checkbox"/> | <input type="checkbox"/> | Seismic Analysis |
| <input type="checkbox"/> | <input type="checkbox"/> | Hazard Classification |
| <input type="checkbox"/> | <input type="checkbox"/> | Other: _____ |

Dam ID: MA-0097
KOLEA RESERVOIR

Inspection No: _____
Date: 4/5/2006

Physical Dam Features: (Check All Applicable. Provide description of Items Observed and/or Take Photos. Indicate photo # in description.)

3. Reservoir:

Level during inspection Reservoir was full; slight flow over spillway. No staff gage so actual level not known ft per _____ (gage / other)
Normal Operating Level/Range _____ ft per _____ (gage / other)
Description: Reservoir pool varies depending on rainfall
Typical Operation ☐ Spillway always flowing ☐ Kept within normal range ☒ Kept Empty ☐ Drained Daily ☒ Only filled by Storms
☒ Other: Reservoir usually empty
Sinkhole in Res.: ☐ # Observed: _____ Size: _____ by _____ in. Deep ☐ Not Visible ☐ None Observed
Description: _____
Staff Gage: Description: No staff gage

Findings:

- ☒ a. The reservoir was not inspected.
☐ b. The reservoir appeared to be in satisfactory condition, no corrective actions are required at this time.
☐ c. The reservoir appeared to be in fair to poor condition and requires corrective action.
☐ d. The reservoir appeared to be in unsatisfactory condition, urgent corrective action is required.

Corrective Actions:

- ☐ e. The staff gage needs maintenance and/or repair. Description: _____
☐ f. A staff gage was not observed at the reservoir. Provide some method of quantifying the water level within the reservoir.
☐ g. A sinkhole was observed in the upstream reservoir. Conduct additional investigations and monitoring to identify the cause, risk and appropriate action.
☐ h. _____

4. Intake Works Description:

Reservoir is on a natural stream
☐ Number of Intakes _____
☐ Intake Culvert / Pipe
Size: _____ in. ☐ DIP ☐ Corrugated Metal ☐ PVC ☐ HDPE ☐ Concrete ☐ Other _____
Control: ☐ Gate ☐ Valve ☐ Flow can either be Shut off or Bypassed
From: ☐ Stream Diversion ☐ Pump ☐ Reservoir ☐ Other _____
☐ Ditch / Flume
Dimension: _____ (Size x Depth) Shape _____
Surface: ☐ Dirt ☐ Wood ☐ Concrete ☐ Lined w/ _____
Control: ☐ Gate ☐ Valve ☐ Flow can either be Shut off or Bypassed
From: ☐ Stream Diversion ☐ Pump ☐ Reservoir ☐ Other _____

Findings:

- ☒ a. The intake works were not inspected.
☐ b. The intake works were not tested.
☐ c. The intake works appeared to be in satisfactory condition, no corrective actions are required at this time.
☐ d. The intake works appeared to be in fair to poor condition and requires corrective action.
☐ e. The intake works appeared to be in unsatisfactory condition, urgent corrective action is required.

Corrective Actions:

- ☐ f. The intake works needs maintenance and/or repair. Description: _____
☐ g. _____

Dam ID: MA-0097

KOLEA RESERVOIR

Inspection No: _____

Date: 4/5/2006

5. Upstream Slope:

(Typical Slope \pm 1 : 1)

Slope Protection: ☐ None ☒ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☐ Liner _____ ☐ Other: _____

☐ Defect in Protection: Description: _____

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed

Description: _____

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☒ None Observed

Description: _____

Sinkholes: ☐ # Observed: _____ Size: _____ and _____ Depth ☐ Not Visible ☒ None Observed

Description: _____

Vegetation: ☒ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # _____ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: Brush on the slope has been recently cut

Findings:

- ☐ a. The upstream slope was not inspected.
- ☒ b. The upstream slope appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ c. The upstream slope appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The upstream slope appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ e. Slope protection needs maintenance or repair. Description: _____
- ☐ f. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair. Description: _____
- ☐ g. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☐ i. The upstream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ j. Tree(s) were observed on the dam embankment. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ k. _____

Dam ID: MA-0097

KOLEA RESERVOIR

Inspection No: _____

Date: 4/5/2006

6. Crest:

Approximate Crest Width: 35'

Access: ☐ None ☐ Walking Path ☒ Roadway, Surface / Width / Usage: Unsurfaced road

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed

Description: _____

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☒ None Observed

Description: _____

Sinkholes: ☐ _____ in. Wide x _____ in. Long x _____ in. Deep ☐ Not Visible ☒ None Observed

Description: _____

Vegetation: ☐ None ☒ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # _____ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: 3" to 6" tall grass on crest

Findings:

- ☐ a. The dam crest was not inspected.
- ☒ b. The dam crest appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ c. The dam crest appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The dam crest appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ e. Access along the crest was satisfactory.
- ☐ f. Access along the crest was not possible. Description: _____
- ☐ g. Rut and/or Gully erosion was observed on the crest, which requires maintenance and/or repair. Description: _____
- ☐ h. A crack was observed on the crest, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ i. A sinkhole was observed on the crest, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☐ j. Portions of the crest were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ k. Tree(s) were observed along the dam crest. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ l. _____

could not see slope

7. Downstream Slope:

(Typical Slope \pm 1 : 1)Access: ☐ lower roadway along toe ☒ roadway to outlet works ☐ walkway to outlet works ☐ None ObservedSlope Protection: ☒ None ☐ Dumped Rock ☐ Rip Rap ☐ Grouted Rip Rap ☐ ConcreteErosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☒ Not Visible ☐ None ObservedDescription: Could not inspect slope due to dense vegetation (bamboo)Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☒ Not Visible ☐ None ObservedDescription: See aboveSinkholes: ☐ _____ in. Wide x _____ in. Long x _____ in. Deep ☒ Not Visible ☐ None ObservedDescription: See aboveVegetation: ☐ None ☐ Low Ground Cover ☒ Bushes or Tall Grass ☐ Trees # _____ ☐ <6" ☐ >6" & <20" ☐ >20"Description: Lots of bamboo on slope. Owner routinely cuts the bambooSeepage: Seep Spot Number 1but it grows very fast, could not inspect slope due to dense vegetation and bamboo.☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☒ Not Visible ☐ None Observed

Flowing, Description: _____

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: _____

Description: _____

Seep Spot Number 2☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☐ None Observed

Flowing, Description: _____

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: _____

Description: _____

Findings:

- ☐ a. The downstream slope was not inspected.
- ☐ b. The downstream slope appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☒ c. The downstream slope appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The downstream slope appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ e. Slope protection needs maintenance or repair. Description: _____
- ☐ f. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair. Description: _____
- ☐ g. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☒ i. The down stream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection. Cut bamboo twice a year OR SPRAY TO KILL
- ☐ g. Tree(s) were observed on the downstream slope. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ h. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ i. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☐ j. The slope was very steep, around a 1 to 1 slope, further study is required to verify slope stability.
- ☐ k. _____

8. Abutments/Toe:

Erosion:

☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☒ Not Visible ☐ None Observed
Description: Could not inspect abutments due to dense vegetation


Cracks:

☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☒ Not Visible ☐ None Observed
Description: See above

Vegetation:

☐ None ☐ Low Ground Cover ☒ Bushes or Tall Grass ☐ Trees # _____ ☐ <6" ☐ >6" & <20" ☐ >20"
Description: Lots of bamboo on abutments. Could not inspect abutments due to dense vegetation

Seepage:

Seep Spot Number 1
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☐ None Observed
☒ Flowing, Description: 20 gpm flowrateWater Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: _____Description: Seep about 10' in front of outlet pipe in the exit channel. Owner should monitor the seep.Seep Spot Number 2
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☐ None Observed
☐ Flowing, Description: _____Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: _____

Description: _____

PLAN VIEW OF
SEEP**Findings:**

- ☐ a. The abutments/toe were not inspected.
- ☐ b. The abutments/toe appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☒ c. The abutments/toe appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The abutments/toe appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ e. Slope protection needs maintenance or repair. Description: _____
- ☐ f. Rut and/or Gully erosion was observed, which requires maintenance and/or repair. Description: _____
- ☐ g. A crack was observed along the abutments/near the toe, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. The abutment/toe area was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ i. Tree(s) were observed along the abutment/toe. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☒ j. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ k. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☐ l. _____

Monitor the seep below outlet pipe for change in flowrate or condition (i.e., seep moves soil).

Dam ID: MA-0097

KOLEA RESERVOIR

Inspection No: _____

Date: 4/5/2006

9. Outlet Works:

Culvert / Pipe

Type / Size: 12" diameter steel pipe

Culvert: ☐ Concrete ☐ Masonry ☐ unlined earth ☐ Other _____

Pipe: ☐ DIP ☐ Corrugated Metal ☐ PVC ☐ HDPE ☐ Concrete ☒ Other steel

Control Type: ☐ Gate ☒ Valve ☐ Other _____

Location: ☒ Control on Upstream side ☐ Control on Downstream side

Seepage: ☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☒ None Observed

☐ Flowing, Description: _____

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: _____

Description: _____

Findings:

- ☐ a. The outlet works were not inspected.
- ☒ b. The outlet works were not tested.
- ☒ c. The outlet works appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ d. The outlet works appeared to be in fair to poor condition and requires corrective action.
- ☐ e. The outlet works appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ f. Seepage/Ponding water was observed. Conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ g. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area. Failures caused by seepage/piping along the outlet conduit are very common and are considered to be a dangerous situation.
- ☐ h. Were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ i. _____
- ☐ j. _____

Dam ID: MA-0097

KOLEA RESERVOIR

Inspection No: _____

Date: 4/5/2006

10. Spillway:

Type:

☐ None ☐ Culvert/Pipe ☒ Channel

Description:

Spillway cut into rock on left abutment

Dimension:

30

ft.

Invert elevation:

ft.

per staff gage

Slope Protection:

☒ None ☐ Grass ☐ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☐ Concrete

☐ Defect in Protection: Description: _____

Approach:

☒ Clear ☐ High Veg. ☐ Trees ☐ Other: _____

Erosion:

☐ Scour ☐ Gully ☐ Headcut ☒ Not Observed ☐ Other: _____

Description: _____

Vegetation:

☒ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # _____ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: _____

Findings:

- ☒ a. The Spillway appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ b. The Spillway appeared to be in fair to poor condition and requires corrective action.
- ☐ c. The Spillway appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

- ☐ d. Slope protection needs maintenance or repair. Description: _____
- ☐ e. The spillway approach was blocked. Clear approach.
- ☐ f. Severe scour erosion was observed which requires maintenance and/or repair.
Description: _____
- ☐ g. A headcut (vertical drop in channel due to erosion) was observed downstream of the spillway. Corrective action is required to prevent this problem from moving upstream.
- ☐ h. Trees are unacceptable in the spillway channel and approach. Take corrective action to address the woody vegetation problem and repair the damaged area.
- ☐ i. Unclear if spillway is adequately sized. Spillway should pass the probable maximum flood. Verify spillway capacity and take corrective action as required.
- ☐ j. _____

11. Down Stream Channel:

Name: _____

Downstream:

☐ Sump ☐ Open Area ☐ Un-Defined Drainage-way ☐ Defined Drainage-way ☐ Other _____

Items along Stream Bank:

☐ None ☐ Road ☐ Houses ☐ Town ☐ Not Inspected

Description: _____

Findings:

- ☒ a. The downstream channel was not inspected.
- ☐ b. The downstream channel appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ c. The downstream channel appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The downstream channel appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

Corrective Actions:

☐ e. _____

Additional Comments:

On the date of this limited visual inspection, there appeared to be no immediate threat to the safety of the dam. No assurance can be made regarding the dam's condition after this date. Subsequent adverse weather and other factors may affect the dam's condition.

FINDINGS:

Conclusion: There is no immediate threat to the safety of the dam.

Recommendations:

- 1) Monitor the seep just below the outlet pipe in the exit channel. Monitor the seep for changes in flowrate or condition (i.e., seep moving material). Owner should have a geotechnical engineer knowledgeable in dams to conduct a detailed evaluation of the seepage conditions.
- 2) Owner need to routinely remove underbrush and bamboo from the downstream slope. Bamboo should be cut and removed at least twice a year OR SPRAY WITH HERBICIDE AND REMOVED.
- 3) Owner should continue with removing brush and trees from the embankment. Grasses should be kept short.

Limitations and Intent of this Dam Safety Inspection:

This Dam Safety Inspection was conducted to assess the general overall condition of the reservoir/dam, identify visible deficiencies, and recommend areas of for monitoring, additional investigative studies and corrective actions. The inspection is based only on visible features/areas of the dam on the day of inspection. This inspection is not a formal phase I or phase II dam safety inspection and does not include a review or evaluation from each specialist of an inspection team, such as a geologists, civil, geotechnical, structural, or hydraulics engineer. The owner should verify the findings of this report and take corrective actions. The owner may submit to the State alternative corrective actions that are certified by a licensed professional engineer in the State of Hawaii experienced in the design and construction of dams. This inspection does not relieve the owner/operator from their responsibility to conduct routine inspections, maintenance, repairs, modifications, monitoring, documentation, and/or investigative studies. The inspection was conducted under the authority of the Hawaii Revised Statutes Chapter 179D, and Hawaii Administrative Rules, Title 13, Chapter 190, titled "Dams and Reservoirs". Questions regarding this inspection should be forwarded to the Hawaii State Dam Safety Program; PO Box 373; Honolulu, Hawaii 96809; Ph. (808) 587-0236.